
DS150C - PROCEDURE Length & Angle Adjustments



ADJUST LENGTH POTENTIOMETER, WITH BOOM FULLY RETRACTED TURN THE CENTER SCREW COUNTER CLOCKWISE TO A SOFT STOP.