

# Product Discontinuation Notification

## iVISOR BSV Series

**PDN-no.** WMC-PDN-2023-0601  
**Announcement date** June 30, 2023  
**Subject** Product discontinuation without replacement

**Reason for discontinuation** The discontinuation is due to problems with the availability of installed components on the market as well as a limited quantity of critical components that have been discontinued for some time.

**Last-Time Buy** November 30, 2023

**Last-Time Delivery** November 30, 2024

**End of Service** November 30, 2025

**Description** There is no suitable 1:1 replacement available

**Products affected** Please see list below

Part#	Product name
607284	iVISOR BSV, 230V, 1AEv
607298	iVISOR BSV, 230V, 2AE
607299	iVISOR BSV, 230V, 2AE-2K
607300	iVISOR BSV, 115V, 1AEv
607301	iVISOR BSV, 24V, 1AE
607302	iVISOR BSV, 12V, 1AE
607428	iVISOR BSV, 24V, 2AE-2K
607429	iVISOR BSV, 12V, 2AE
608305	iVISOR BSV, 115V, 2AE
608324	iVISOR BSV, 24V, 2AE

For further questions or any additional assistance, please contact your key account manager or your local sales office directly. All contacts for sales representatives are available here: [WMC Global Network](#)